


BUREAU VERITAS
Certification



SERVICIOS Y SUMINISTROS CENTRÍFUGOS S.R.L.

SEDE CENTRAL: MALVINAS ARGENTINAS 2253, VICTORIA, SAN FERNANDO, PROVINCIA DE BUENOS AIRES
ARGENTINA

This is a multi-site certificate, additional site details are listed in the appendix to this certificate

*Bureau Veritas Certification certify that the Management System of the
above organisation has been audited and found to be in accordance
with the requirements of the management system standards detailed below*

Standard

ISO 9001:2008

Scope of certification

**SERVICIO DE MANTENIMIENTO Y REPARACIÓN DE EQUIPOS: SEPARADORES
CENTRÍFUGOS, INTERCAMBIADORES DE CALOR Y BOMBAS CENTRIFUGAS.**

Certification cycle start date: **08 de Marzo de 2016**

Subject to the continued satisfactory operation of the organisation's Management System,
this certificate expires on: **14 de Septiembre de 2018**

Original certification date: **08 de Marzo de 2010**

Certificate No. **AR-O235107**

Version 00, Revision date: **01 de Marzo de 2016**


Ing. Marta G. Paz

OAA_v

Organismo
Argentino de
Acreditación

Organismo de Certificación de
Sistemas de Gestión de Calidad
OCSCG 003




**BUREAU
VERITAS**

Managing and Issuing Office: Bureau Veritas Argentina S.A. - Av. L. N. Alem 855, Piso 2°- Ciudad Autónoma de Buenos Aires, Argentina

Further clarifications regarding the scope of this certificate and the applicability of the management system requirements may be obtained by consulting the organisation. To check this certificate validity please call +54 11 4000 8100.

BUREAU VERITAS
Certification



SERVICIOS Y SUMINISTROS CENTRÍFUGOS S.R.L.

Standard

ISO 9001:2008

Scope of certification

SEDE CENTRAL: SERVICIO DE MANTENIMIENTO Y REPARACIÓN DE EQUIPOS: SEPARADORES CENTRÍFUGOS, INTERCAMBIADORES DE CALOR.

*Permitted Exclusions: 7.3 Diseño y Desarrollo.

SEDE CENTRAL	MALVINAS ARGENTINAS 2253, VICTORIA, (1644) SAN FERNANDO, PROVINCIA DE BUENOS AIRES ARGENTINA	SERVICIO DE MANTENIMIENTO Y REPARACIÓN DE EQUIPOS: SEPARADORES CENTRÍFUGOS, INTERCAMBIADORES DE CALOR.
SITIO 2	MALVINAS ARGENTINAS 2137, VICTORIA, (1644) SAN FERNANDO, PROVINCIA DE BUENOS AIRES ARGENTINA	SERVICIO DE MANTENIMIENTO Y REPARACIÓN DE EQUIPOS: BOMBAS CENTRÍFUGAS. DEPÓSITO.

Certificate No. AR-O235107

Version 00, Revision date: 01 de Marzo de 2016


Ing. Marta G. Paz

OAA

Organismo
Argentino de
Acreditación

Organismo de Certificación de
Sistemas de Gestión de Calidad
OCSGC 003



BUREAU
VERITAS

Managing and Issuing Office: Bureau Veritas Argentina S.A. - Av. L. N. Alem 855, Piso 2° - Ciudad Autónoma de Buenos Aires, Argentina

Further clarifications regarding the scope of this certificate and the applicability of the management system requirements may be obtained by consulting the organisation. To check this certificate validity please call +54 11 4000 8100.